

From: [Stephen Tzhone](#)
To: [Scott Huling](#)
Cc: [Carlos Sanchez](#); [John Meyer](#); [Gloria-Small Moran/R6/USEPA/US@EPA](#); [Casey Lockett](#); [Jon Rauscher](#); [kdbecher@usgs.gov](#)
Subject: Arkwood gw remediation
Date: 05/29/2012 01:01 PM
Attachments: [Operation Manual.pdf](#)
[Atlas Copco manual.pdf](#)
[Groundwater Remediation Summary.docx](#)
[Third Five Year Review.pdf](#)
[2011-04-04_5_yr_rev_comm_final.pdf](#)

Hi Scott,

1) Attached is a draft outline for the Groundwater Remediation Summary report that is due to EPA R6 by June 4, 2012. Copies of the pilot system operation manual (with and without the ozone generator and compressor/oxygen concentrator) are also provided as an fyi.

Currently, the pilot system operations no longer include production and injection of ozonated water into the subsurface. In addition, the PRP (McKesson) is recommending to discontinue injection of non-ozonated water on the main site, as to allow for measurement of potential rebound effects and to provide better quantification of PCP concentrations emanating from New Cricket Spring. Details of their recommendations and conclusions will be in the upcoming report.



Groundwater Remediation Summary.docx Operation Manual.pdf Atlas Copco manual.pdf

2) The last five year review, page 8 (pdf p.18), details the gw remediation status as of 2011. ADEQ also had comments regarding the five year review (attached), several which they have communicated to us that do not appear to be incorporated... R6 would be interested in ORD's perspective on these comments, esp. the ones dealing with Section VII Assessment, Section VIII Deficiencies, and Section IX Recommendations and Follow-up Actions.



Third Five Year Review.pdf 2011-04-04_5_yr_rev_comm_final.pdf

*Scott: I've included the other team members on cc as an fyi on the status of the gw remediation.

Thanks,

Stephen L. Tzhone
Superfund Remedial Project Manager
USEPA Region 6 (6SF-RA)
214.665.8409
tzhone.stephen@epa.gov